

DATE: Tuesday, April 22, 2014

HOSTED BY: PSE&G

TOPIC(s): Towers for Power and H&S (Helicopters and Safety)

SPEAKER: Randy Koncelik

LOCATION: PSE&G Training Facility
234 Pierson Avenue
Edison, NJ 08837

PROGRAM

5:00 Registration
5:30 Introduction to PSE&G – Randy Koncelik
6:30 Dinner & Business Meeting
7:15 Technical Presentation
Towers for Power and H&S (Helicopters and Safety)

Topic

PSE&G is responsible for the construction of the transmission towers along 45 miles of an existing Right of Way from the Pennsylvania border to their Roseland Switching Station. PPL Electric Utilities is constructing the Pennsylvania part of the line.

The project had unique construction constraints due to terrain and wetlands. At times, helicopters were utilized to demolish existing towers and for the construction of the new towers. Helicopters also played a vital role in support services. Integrating helicopters into the project required additional health and safety and expertise not usually associated with electrical upgrade projects.

Attend the meeting on April 22nd to hear Randy discuss the S-R project and the unique health and safety challenges encountered on this ground breaking project.

ABOUT THE SPEAKER

Randy Koncelik, a project manager with the transmission group at PSE&G for 20 years, has been managing the Susquehanna-Roseland 500 kV Upgrade project.



Directions

**PSEG Edison Training and Development Center
234 Pierson Avenue
Edison, New Jersey 08837**

From Garden State Parkway (South) -

- Take exit 130 to Route 1 South
- Follow Route 1 South
- Pass under I-287 and get off Route 1 at the exit for Bonhamtown
- Make a right at the top of the exit ramp
- Cross over Route 1 and take second left onto Morris Avenue
- Pierson Avenue is the sixth left off of Morris Avenue

From Garden State Parkway (North)

- Use exit 127 - located at the north end of the Driscoll Bridge
- At the exit follow the signs for Route 440 (I-287)
- Take I-287 North to Route 1 north exit
- Merge onto Route 1 North and stay in right lane
- Take ramp to Pierson Avenue
- At end of exit ramp make a left into the PSE&G compound and follow the driveway to its end

From I-287 (South) -

- Use exit for Route 1 North (Exit 1A - Edison, NJ)
- Proceed up Route 1 North and make first right after passing through the I-287 interchange; stay in the right lane
- Take ramp to Pierson Avenue
- At end of exit ramp, make a left into the PSE&G compound and follow the driveway to its end

440 West, I-287 (North) -

- Take I-287 North to Route 1 north exit
- Merge onto Route 1 North and stay in right lane
- Take ramp to Pierson Avenue
- At end of exit ramp make a left into the PSE&G compound and follow the driveway to its end

From NJ Turnpike (North or South)



- Exit 10 to I-287 North
- Take I-287 west to Route 1 north exit
- Merge onto Route 1 North and stay in right lane
- Take ramp to Pierson Avenue
- At end of exit ramp make a left into the PSE&G compound and follow the driveway to its end

From Route 1 (North) -

- Proceed up Route 1 North
- Pass under the I-287 overpass and stay in the right lane
- Get off on the Pierson Avenue exit
- At end of ramp, make a left into the PSE&G compound and follow the driveway to its end

From Route 1 (South) -

- Follow Route 1 South
- Pass under I-287 and get off Route 1 at the exit for Bonhamtown
- Make a right at the top of the exit ramp
- Cross over Route 1 and take second left onto Morris Avenue
- Pierson Avenue is the sixth left off of Morris Avenue



COST

\$25 for members

\$10 for student & unemployed members

\$35 for non-members

Pay at door by cash or check, payable to "AHMP-NJ"

REGISTRATION

Reply to the Chapter Secretary by email at RSVP@achmm-nj.org

Or register online at <http://www.ahmpnj.org/Default.aspx?pagel=1325826>